

Download Chrysler Pt Cruiser 2001 2003 Repair Service Manual Pdf

View and Download Chrysler PT Cruiser service & repair manual online. PT Cruiser Automobile pdf manual download. P0340 - Camshaft position sensor circuit malfunction.; P0457 - Evaporative emission control system leak detected (fuel filler cap loose/off) There is a bulletin #0398 posted on 05/12/2003 for P0457 - Malfunction indicator lamp (mil) illumination with diagnostic trouble codes p0442, p0455, p0456, p0457, p1442 or check fuel cap lamp illuminated with diagnostic trouble code p0457. El Club de Diagramas es dónde los técnicos intercambian y comparten diagramas, manuales de servicio y todo archivo de información técnica útil para las reparaciones electrónicas. 1925–1996: Chrysler Corporation. The Chrysler company was founded by Walter Chrysler on June 6, 1925, when the Maxwell Motor Company (est. 1904) was re-organized into the Chrysler Corporation. Chrysler had arrived at the ailing Maxwell-Chalmers company in the early 1920s, hired to overhaul the company's troubled operations (after a similar rescue job at the Willys-Overland car company). - Chrysler Pt Cruiser 2001 2003 Repair Service Manual Pdf